		AFET	Y OF SCHOOL BUILDING	
	(To be filled by the Head of School/ Institute) 1. Name of the School: GREEN LAND CONVENT SCHOOL			
	2. Location : PHASE-II, URB.	: Phase-II, urban estate, dugri, ludhiana		
	4. Plinth Area : 6000 sq. yard / Land Area 54475.59 sq. ft. 5. Number of Storey's : Basement/Ground/First/Second/Third Floor			
	6. Year of Construction of Building: 2007			
	7. If the building has been constructed upon the Supervision of the qualified Engine the following details may be given: a) Name of the Engineer with qualification	ieer,	. VIRENDER KUMAR (Civil Engineer)	
	b) Address of Engineer		IV, 1132, DARESI ROAD, LUDHIANA	
	c) Set of Structural drawings used in the construction, if available d) Name & address of Architect with qualification		: Enclosed : Mrs. SHELJA GUPTA	
	8. Whether the building has been constructed for the purpose:			
	a) Schools:	:	Yes	
	b) Residential Purpose and converted			
	for use as a School	:	No	
Ó	9. Materials used for roofs			
	a) R.C.C. Slabs/R.B.C Slabs	•	Yes	
	b) R.S. Joist & Battons	:	No	
١.	c) Wooden joists & Battons	:	No	
	10. Materials used for walls		•	
	a) Mud Mortar: (YES/NO)		No	
	b) Cement Mortar: (YES/NO)		Yes	
	c) Plaster (i) Lime Mortar: (YES/NO) (ii) Cement Mortar(YES/NO)		No Yes	
	11, Flooring			
	a) Conglomerate : (YES/NO)		Yes	
	b) Terrazo : (YES/NO)		No	
	c) Brick Paving. : (YES/NO)		No	

12. A detailed drawing indicating dimensions of the rooms principal convent School Alongwith size and location of doors and windows:

Signature with Stamp of the seal of the School/Institution.

0/2023-24/60

PART-II 6/5/2 3.3 (To be filled by the S.D.E.)

- a) I have visited the above mentioned school on dated OS 0.5. and have visually inspected it from all angles of safety and find it fit for normal use as School buildings.
- b) In case any addition/ alteration or expansion and modifications to this buildings is to be carried out, the same be carried out under the supervision of a qualified Engineer and this certificate may be reobtained after the completion from the undersigned.
- c) In case the building is affected by food, or if there is settlement of walls/ foundations o. sagging of roofs etc. immediate inspection of the undersigned by arranged to check the stability and safety of the building.

d) This building can be safety occupied for normal use upto 31/02/2014 (indicate upto which it can be used)

From the Amelian Str. From Str. Str. Br. LUDHANA.

Sub Divisional Engineer

For Sant Kirpal Vidyak Mission (Regd.)

Chairman

Green Land Convent School Phase-II Dugri, Ludhiana.